


## **BOTTOM VIEW**



Drawings are prepared for catalogue study.

Diawings are prepared for eatalogue study.							
Changes							
	a	Bumper was changed		10.03.2011			
	0	First drawing		30.09.2009			
	Issue	Changes		Date	Drawn by	Checked by	Approved by
PART WEIGHT:		Do not scale this drawing	Bolt/Stud	<b>⊗</b> c	ombo stud	Air inlet	Threaded hole
	Kg.	All rights of this document are the property of AKTAS A.S. it can not be used copied zeroriouted, made available to any their pany in whole or part without written permission of AKTAS A.S.			ORDER NO: 123562		
PART NAME: 39373-02 P SERVICE ASSEMBLY (095.0491)							